

Turbine Outlet Temperature Indicator

FAA STC # SR02541LA

Applicable Aircraft: MD Helicopters 369FF

2016 Pricing: *See Precision Heli-Support, LLC price list*

Installation: less than 8 hrs.

System Description: The TOT indicator replaces the MD Helicopters TOT indicator with a digital/analog indicator that has exceedance monitoring.

- Standard indicator size. Replaces either a clamp mount or may utilize a standard bezel.
- The indicator is a digital with analog and digital displays that are more accurate with a higher resolution and provides exceedance monitoring.
- The indicator does not require re-calibration or circuit resistance adjustment at any time.
- Potential over-temperature event: To warn the pilot of a potential over-temperature.
- Actual over-temperature event: To alert the pilot of an over-temperature event.
- Reminder of recorded over-temperature event: After an over-temp event has occurred.
- May utilize the existing thermocouple wires if found acceptable for continued use.
- White backlighting.

