

Oil Pressure Indicator & Transducer Upgrade

FAA STC # SR02536LA

Applicable Aircraft: MD Helicopters 369HE/HS/HM/D/E/F/FF/500N

2016 Pricing: *See Precision Heli-Support, LLC price list*

Installation: 16-20 hrs.

Part Number: 4344-3187-KIT

System Description: The indicator is a pressure transducer driven indicator and utilizes only a 14" flexible oil line installed in the engine bay. The blue-white indicator backlighting allows for clear readability during night operations.

- Removes the MD Helicopters existing "wet lines" and stainless steel line that runs from the engine oil pressure port to the back of the aircraft instrument panel.
- Removes all chances of oil leaking from the oil pressure indicator system within the aircraft cabin.
- Removes the inspection procedures for the MD Helicopters plastic oil lines thru out the cabin.
- Indicator is a direct replacement for the MD Helicopters indicator. Also may utilize a 4-hole mounting bezel.
- Transducer and oil line are installed in the aircraft engine compartment which allows for ease of installation and maintenance.
- Reduces time in inspection resulting in a saved profit instantly.

